

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 324 Const Calendar Day: 770 Date: 14-Jul-2014 Monday Inspector Name: Liu, Tai-Lin Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 AM 03:30 PM Break: 00:30 Over Time:

Federal ID: Location:

Reviewer: Awal, Mohammad Approved Date: 17-Aug-14 Status: Approved

Weather

 Temperature
 7 AM
 60 - 70
 12 PM
 70 - 80
 4PM
 70 - 80

 Precipitation
 Condition
 Clear

Working Day 🗸 If no, explain:

Diary:

Tower Activites

Tower Base Works (7/14/14, Monday - Clear day):

* CCC painting works:

- Attended staff meeting this morning.
- No METS paint inspector in the field yet. CCC Tony was in pier 7 for paint testing, not in the field today.
- CCC two painters continued painting in elevation 18 tower façade area. They will move to elevation 23 to paint the the façade inside area.
- Two CCC painters performed preparation work at elevation 28 & 33 façade area.
- CCC 6 painters worked 10 hours today.
- CCC painter Billy was painting the elevator door today at the fender concrete area.

Paint Crew: Billy Gatewood, Joege Flones, Javier Alvag, Recardo Pasalla, Manuel & Eric - 10 hours.

* Saw ABF cleaning crew at tower base area (above 53 meter exterior of shaft, See pictures) - Refer to Laraine's diary for detail.

ABF's crew: Rogelio Rodriguez, Aurelio Rodriguez (not in PMIV system), Guillermo Limon (Labor Forman), Javier Medina, Danny Schwartz.

- * Saw IRWs Paul & Donald Plumb at job site.
- * Saw 3 electrican worked on elevator area.
- * Crane operator Neil Caldwell & helper Justin at barge stand by for any lifting work needed.
- * Performed paper work including RFI/Submittal PMIV works at the office. Left office around 03:40 P

04-0120F4 Bid Item: 053 T-L01-DSE.053 Tower Lift 01 Diaphram Tower SE Erect structural steel (bridge tower)

AMERICAN BRIDGE/FLUOR, A JV

Labor
Trade Class Name RT Hrs OT Hrs DT Hrs Total Remarks Dispute



Page 1 of 4

Run date 22-Nov-14 **Time** 12:02 PM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item


Job Name: 04-0120F4 Inspector Name: Liu, Tai-Lin Diary #: 324 Date: 14-Jul-2014 Monday Contractor: AMERICAN BRIDGE/FLUOR, A JV JNM 8 00 0.00 0.00 8.00 Ironworker DONALD PLUMB Ironworker JNM PAUL FAMBRINI 8.00 0.00 0.00 8.00 Semi-Skilled Laborer JNM FERMIN MEDINA 0.00 0.00 0.00 0.00 GEN AARON KENT 0.00 0.00 Ironworker 0.00 0.00 Semi-Skilled Laborer JNM LUIS Jimenez 0.00 0.00 0.00 0.00 Semi-Skilled Laborer JNM DANNY SCHWARTZ 8.00 0.00 0.00 8.00 Semi-Skilled Laborer APP JAVIER MEDINA 8.00 0.00 0.00 8.00 Semi-Skilled Laborer FOR **GUILLERMO LIMON** 8.00 0.00 0.00 8.00 Semi-Skilled Laborer APP ROGELIO RODRIGUEZ 8 00 0.00 0.00 8 00 Semi-Skilled Laborer JNM **CARLOS MONTEJANO** 0.00 0.00 0.00 0.00 Semi-Skilled Laborer APP JOSE AVILA 0.00 0.00 0.00 0.00 Semi-Skilled Laborer JNM VICTOR HERNANDEZ 0.00 0.00 0.00 0.00 Ironworker FOR JAMES STURGEON 0.00 0.00 0.00 0.00 **Equipment** Rental Company **Equipment ID** Description RT Hrs OT Hrs ST Hrs IT Hrs Remarks Dispute AMERICAN BRIDGE/FLUOR, A JV Contractor: *E0020562 WELDING EQUIPMENT No 0.00 0.00 0.00 0.00 *E0030562 WELDING EQUIPMENT No 0.00 0.00 0.00 0.00 WELDING EQUIPMENT *E0010562 No 0.00 0.00 0.00 0.00 2292 WELDER, 600 AMP No 0.00 0.00 0.00 0.00 WELDER, 600 AMP 2293 No 0.00 0.00 0.00 0.00 04-0120F4 T-L01-ENE.078 Tower Lift 01 External Paint Tower NE Bid Item: CERTIFIED COATINGS COMPANY 04-0120F4 Bid Item: T-L05-ENE.078 **Tower Lift 05 External Paint Tower NE** CERTIFIED COATINGS COMPANY 04-0120F4 Bid Item: T-HEA-ENE.078 **Tower Head External Paint Tower NE** CERTIFIED COATINGS COMPANY CCO-355 Bid Item: 001 0-CIC-EFA.355 **CIC - Elevator Impacts - USA Hoist** AMERICAN BRIDGE/FLUOR, A JV

Attachment



Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Liu, Tai-Lin Diary #: 324 Date: 14-Jul-2014 Monday



Three electricians worked on electric line on tower elevator





CCC painter Joge performed painting on inside façade area elevation 18



Painting inside the façade area



ABF labers performed cleaning exterior of tower on east side area near 53 meter area



CCC painters (2) performed prep. Works on Elev. 28 & 33 area

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Liu, Tai-Lin Diary #: 324 Date: 14-Jul-2014 Monday



CCC transported tool to el. 28 façade area



CCC Billy performed painting on elevator door at fender concrete area